




FIG. 1





1010-0006-USA  
Serial No. 10/810,247  
J. M. Weinick, LLC; (973) 533-1616  
REPLACEMENT SHEET

2/9

FIG. 2






FIG. 3





1010-0006-USA  
Serial No. 10/810,247  
J. M. Weinick, LLC; (973) 533-1616  
REPLACEMENT SHEET

3/9



**FIG. 4**



4/9

FIG. 5






FIG. 6





5/9


FIG. 7





1010-0006-USA  
Serial No. 10/810,247  
J. M. Weinick, LLC; (973) 533-1616  
REPLACEMENT SHEET

6/9







1010-0006-USA  
Serial No. 10/810,247  
J. M. Weinick, LLC; (973) 533-1616  
REPLACEMENT SHEET

7/9


*FIG. 9A*




*FIG. 9B*




*FIG. 9C*




*FIG. 9D*




*FIG. 9E*




*FIG. 9F*




*FIG. 9G*




*FIG. 9H*



*FIG. 9I*



*FIG. 9J*



CENTER LINE



1010-0006-USA  
Serial No. 10/810,247  
J. M. Weinick, LLC; (973) 533-1616  
REPLACEMENT SHEET

8/9

FIG. 10




FIG. 11

POSSIBLE POSITION OF THE ROVER






FIG. 12

9/9

